

Engineering material and their properties

- 1.1 Material classification into ferrous and non ferrous category and alloys.
- 1.2 Properties of materials: physical, chemical and mechanical
- 1.3 Performance requirements
- 1.4 Material reliability and safety

Corrosion - potential dynamic polarisation
Electro impedance spectroscopy

Ferrous material

'Ferro' means 'iron'. The materials consist of iron are called ferrous materials. The atomic number of iron is 26. It is a d-block element in the periodic table. There are different types of ferrous materials like vanadium steel, stainless steel, high strength steel and spring steel. Except these light weight ferrous materials are also considered under this category like aluminium based ferrous material, silicon based ferrous materials and alloys, high entropy alloy (HEA) etc.

Non-ferrous materials

Those materials or alloys which don't contain ferrous or iron called non-ferrous alloys. These are Be (beryllium) based, Al (aluminium) based and Ti (titanium) based alloys. These materials have low density and low mechanical properties compared to the iron based materials and alloys.

Special properties of non-ferrous alloys

High corrosion resistance

High electrical Conductivity

High thermal Conductivity

The major disadvantages of these alloys have energy requirement for the extraction from the ore.

Ex:- One ton aluminium need 76,000 kWh for processing from ore to primary material. This is five times the making need of steel. But the aluminium & casts are needed only 6% of this energy to prepare primary materials.

Properties of materials

Physical properties- There are the standard properties related with the chemistry of the materials.

i) state- The materials can be in solid, liquid or gaseous states. There are many factors hidden within each state.

ii) Density- The mass of the material per unit volume. Called density

$$\text{Density} = \frac{\text{mass}}{\text{volume}}$$

There are high and low density materials. The density of iron is 7.86 g/cm^3 . The density of titanium is 4.5 g/cm^3 . The high density materials here heavy engineering applications. The low density materials are used in aerospace industries, biomaterials or manufacturing of domestic appliances.

iii) Magnetism- Magnetism is one among the crucial properties. These are utilized in versatile fields like electric field applications, magnetic field applications, characterization techniques, advance technology like hyperloop and superconductivity in laptop computers. All the magnetic materials have positive susceptibility. According to the magnetic properties magnetic materials are three types

- (1) Diamagnetic material
- (2) Paramagnetic material
- (3) Ferromagnetic material

The diamagnetic materials have negative susceptibility but para and ferromagnetic materials have +ve susceptibility. The para and ferro materials are very magnetized along the direction of magnetic field but the diamagnetic materials are magnetized of opposite direction of the magnetic field. Iron, Nickel and Cobalt are magnetic materials of high susceptibility.

Solubility:- The mixing of materials with other materials is called solubility. The extent of solubility is different for different materials. The solvent are also different. There are solid solution (Brass, Bronze), liquid solution (C syrup) and gas solution (air). The materials of alloys are generally digested in acids (Strong acids). The polymers are dissolved in organic solvent (acetone, benzene, toluene) and other elements or components are dissolving in polar solvent like water.

Viscosity:- The resistance provided by the materials to flow is called viscosity. The viscosity is temperature dependence. It increases with increase in temperature.

Mechanical properties

The mechanical properties of materials (metals or alloys) are strength, ductility, Creep strength, fatigue and fracture. The strength are Compressive strength, tensile strength, shear strength, yield strength.

1. Strength:- It is resistance offered by the materials when subjected to external loading. So stronger the material, greater load it can withstand.

The maximum stress that any material will withstand before destruction is called ultimate strength.

II Elasticity :- The elasticity of a material is its power of coming back to its original position after deformation when the stress of the solid is removed. Elasticity is the tensile property of the materials. So after the stress of materials can endure without taking up some permanent set or called elastic point.

III Stiffness :- The resistance of the material to the deflection is called stiffness or rigidity. Steel is more stiffer than aluminium. Stiffness is measured by Young's modulus of elasticity. Higher value of Young's modulus, stiffer the material.

IV. Plasticity :- The plasticity of the material is its ability to undergo some degree of permanent deformation without any failure. Plastic deformation will take place only after the elastic range has been exceeded. Plasticity is an important property and widely in several mechanical process like forming, shaping, extruding and any other hot and cold working process. In general plastic deformation increases with increasing temp. and is a favourable property of material for secondary forming process.

Due to this properties various metals can be transformed into different products & can be transformed into different products & required shape and size. The conversion into desired shape and size is affected either by the application of pressure, heat or both.

V Ductility :- Ductility of a material enables it to draw out into thin wire on applying of the load. Mild Steel is a ductile material. The wire of gold, silver, Copper, aluminium etc. are drawn by extrusion or by pulling through a hole in a die due to ductile

property. The ductility decreases with increase of temperature.

The percent of elongation and the reduction in area in tension is often used as empirical measure of ductility.

V **Malleability** :- Malleability of material is its ability to be flattened into thin sheets without cracking of hot or cold working. Aluminum, copper, tin, lead, steel etc are malleable metals.

Lead can be readily rolled and hammered into thin sheets but cannot be drawn into wire. Ductility is a tensile property, whereas malleability is a compressive property. Malleability increases with increase in temperature.

VI **Brittleness** :- The brittleness of material is the property of breaking without much permanent distortion. There are many materials, which break or fail before much distortion take place. Such materials are brittle e.g. glass, Cast iron.

Therefore, a non-ductile material is said to be a brittle material. Usually the tensile strength of brittle material is only a fraction of their compressive strength. A brittle material need not be considered as lacking in strength. It only shows the lack of plasticity. On stress-strain diagram these materials don't have yield point & strength point at E' is small.

VII **Toughness** :-

A tougher material is its ability to withstand both plastic and elastic deformation. It is a highly desirable quality for structural and machine parts to withstand shock and vibration. Mn Steel, wrought iron, mild steel are tough materials.

For ex:- if a load is suddenly applied to a piece of mild steel and then to a piece of glass the mild steel will absorb much more energy before failure occurs. Thus mild steel is said to be much tougher than glass.

Toughness is a measure of the amount of energy material can absorb before acted fracture or failure takes place. The work done against

by the material is called "modulus of toughness".
Toughness is also resistance to shock loading. It is measured by a special test on impact testing machine.

Hardness:-

Hardness is closely related to strength. It is the ability of a material to resist scratching, abrasion, indentation or penetration.

It is directly proportional to the tensile strength and is measured on special hardness testing machines by measuring the resistance of the material against penetration of a indenter of special shape and material under a given load. The different scales of hardness are Brinell hardness, Rockwell hardness, Vickers hardness etc.

Hardness of the material does not directly relate to the hardness ability of the metal. Hardenability is indicative of the degree of hardness that the metal can acquire through the hardening process that is heating and quenching.

Hardenability:-

Hardenability is the degree of hardness that can be imparted to metal by process of hardening. A metal capable of being hardened throughout its structure is said to have high hardenability. The metal is heated above a certain temperature and then suddenly quenched in a cold oil or water bath.

Impact Strength

It can be defined as the resistance of the material to fracture under impact loading i.e. under quickly applied dynamic loads. Two standard test are normally used to determine their properties i.e.

i. The Izod Impact Test.

ii. The Charpy Test.

Resilience

Resilience is the capacity of material to absorb energy elastically. On removal of load the energy stored is in a spring.

The maximum energy which can be stored in a body upto elastic limit is called the point resilience. The quantity gives capacity of materials to bear shocks and vibration. The strain energy stored in a material of unit volume gives point resilience and is measured by work stretching.

Chemical properties

I. Toxicity: A measure of a material's ability to damage or ~~destroy~~ disrupt the metabolism of living tissue, may be acute or chronic. Can be determined by contact inhalation, ingestion or injection.

II. Chemical resistance: A material's ability to withstand degradation from acids, solvents, water or oxygen. Corrosion is a species process generally marked by weight change, discoloration, cracking or change in mechanical properties.

III. Corrosion resistance: Corrosion is an electrochemical process that is closely related to the activity series. An ion high on the list will replace a metal lower on the list.

$$\text{Mg} > \text{Al} > \text{Zn} > \text{Cr} > \text{Fe} > \text{Sn} > \text{Ni} > \text{Cu} > \text{Ag} > \text{Au}$$

Corrosion is strongly independent on environment, material.

IV. Combustibility: A material's ability to catch fire and burn, important for organic materials and reactive materials (specially finely divided)

V. Passivity: The loss of chemical reactivity by some active metals and alloys, frequently by formation of a thin oxide surface coating.

Bio-compatibility: The using of materials ~~so~~ on on the human body without eliciting a rejection response from the surrounding body tissues. Includes materials made of polymers, metals, ceramics and composites.

Materiel of selection and reliability

All the products are made up of materials. So the material of selection for the fabrication of product is important. The materials are basically metals, polymers, adhesive and many other. The selection of right materials meets the needs of the customer and sufficiently reliable. An understanding of the response applied stress over time on it.

Acceptable things for material of reliability

- ① Supplier data sheets and reliability forms.

The design team may select materials according to their experience according to the data sheet provided by the supplier. The supplier's additional information are considered, especially shift, drift, degrade, deteriorate or corrode; over time is considered. Engineering experience along with sufficient supplier characteristics result may indicate there is little risk for the given application.

- ② Materiel of performance

Metals/ alloys

- ① Cavitation is a pitting erosion due to liquid/gas bubble collapse and resulting in a high force impact on the metal surface.
- ② Corrosion given the process and use environment including the presence of contaminants.
- ③ Cracking and Crack propagation given shock vibration, stress concentration or cyclic loading.
- ④ Deformation due to applied loads or stress relaxation after forming.
- ⑤ Embrittlement due to chemical interactions in cyclic loading.

- ⑥ Fatigue most often due to cyclic loading
- ⑦ fracture Can be ductile fracture due to cyclic loading Or of shear fracture due to excessive loading or a combination.
- ⑧ friction an increase or decrease in friction depending on the application due to lubricating surfaces, contamination, tolerance, surface finish changes
- ⑨ wear often due to abrasion in the normal course of use for some applications causing a change in dimension over time.

Ferrous materials and alloys

The iron based materials are called ferrous materials. This includes all types of iron and steel related materials. They are classified as

i. Pig iron - It is the basic material from which wrought iron and steel get manufactured. It is obtained from blast furnaces in crude and impure form.

ii. Cast iron - It is a refined form of pig iron obtained from cupola furnace.

iii. Wrought iron - It is virtually pure iron containing large number of minute threads of slag by panes to each other, thereby giving the metal a fibrous appearance when broken.

iv. Carbon Steel - This is the carbon based steel with the composition at various percentage-

- a. Low carbon steel / mild steel
- b. Medium carbon steel
- c. High carbon steel

v. Alloy steel - When some alloying elements like Ni, Cr, Mn, V, W etc. are added to the carbon steel to obtain some specific properties, the produced steel is called alloy steel.

Properties of ferrous materials

- ① Ductile
- ② Great tensile strength
- ③ Visually magnetic
- ④ Good resistance to corrosion
- ⑤ A better like Colored

- Uses of ferrous materials
- ① The ferrous materials are found in solid and liquid phase. They are all crystalline. So they should have mechanical properties and low cost so that it permits them for heavy engineering application.
 - ② The composition of the steel decides its mechanical properties. The ultimate tensile strength of painted steel is 425 - 860 MPa, yield strength 172 - 690 MPa, elongation 12 - 40% and hardness of HRB. The ferrous materials consist of Carbon, manganese, phosphorus, sulfur, silicon, chromium, nickel, molybdenum etc. Carbon and Chromium are active element for corrosion resistance. Ni used as stabilizer.
 - ③ Due to the mechanical properties of the working steel is used to make long lasting skyscrapers. They are also used for making tools, vehicles engines, pipeline, container, aeroplanes etc.
 - ④ The railway tracks and various equipment are also made by steel.
 - ⑤ Due to the magnetic properties, it is also used as magnetic materials.

Low Carbon Steel

This is the non-alloy steel because Carbon is the alloying element there. Except Carbon other elements in the non-alloy steel are sulphur, silicon and manganese. The low carbon steel contain Carbon of $0.1\% \text{ to } 0.25\%$. They are pretty low cost and very well suited for bending operation. The surface hardening can be increased through carburizing. The low cost and malleability low carbon steel are widely used for the making of nuts, bolts, forging and medium loaded objects. They are not heat treated because the hardenability is too low to produce martensite. They are used in the form of coil or roll sheet. The microstructure consists essentially of ferrite.

Mechanical properties of low carbon steel

<u>Y.S. (MPa)</u>	<u>T.S. (MPa)</u>	<u>% elongation</u>
200 - 300	300 - 370	28 - 40

The excellent formability of these steels make them suitable for cold form applications such as stamping of automobile and refrigerator bodies, thin cans and corrugated sheet.

Dual phase steels: By the development of the strength of the low carbon steel dual phase steel is formed without an appreciable loss of formability. The property of dual phase steels are

- I. The absence of a discontinuous yield point.
- ii. A low ratio of yield strength to tensile strength.
- iii. A high work hardening rate.
- iv. A high tensile strength.
- v. A large uniform elongation.

Low carbon steels are annealed in the inter critical ($\alpha + \gamma$) region of the Fe-C phase diagram and then cooled rapidly enough to convert the austenite part to both martensite. The final microstructure consists of 15-20% of martensite is good in a fine-grained bainitic matrix. The typical mechanical properties

<u>Y.S. (MPa)</u>	<u>T.S. (MPa)</u>	<u>% elongation</u>
350	650	30

Medium carbon steel

The medium carbon steel contains 0.25% to 0.6% of carbon. The higher carbon content increases their strength and hardness compared to low carbon steel. The increase of carbon and Mn allowing tempering and quenching. The medium carbon steel is used in automotive industries to make gears, axles, shafts, bolts, nuts, screws etc. Steel ranging 0.4-0.6% of carbon are suitable for everything related to components and tools.

High Carbon Steel

The carbon percentage of high carbon steel is 0.6% to 1%. The carbon content varies according to different sources. Some have more hard grain. These are the strongest of this group, making it suitable for applications where resistance against mechanical material wear is needed. The other quality of high carbon steel is their tendency to keep a shape. This is why tool steel has lot of different applications in the field of engineering. At the downside the bending, ductility and impact hardness are compromised to steels with less carbon. Steels are also classified by case hardening and high carbon steel, overheat. The shape keeping quality makes them useful as spring. Other uses cases includes blades, nail steel wire rope, wear resistance plates, cutting tools etc.

Alloy Steels and alloying elements

Alloy steels makes up another subgroup of ferrous materials. Specific alloying elements are Chromium, nickel, silicon, copper, titanium etc. Each has either own effect or material properties.

Chromium:

- Responsible to making standard steels
- Above 11% of chromium make a steel corrosion resistance
- In material a layer of chromium oxide is formed. It protects from oxidation and corrosion resistance
- It also increases tensile strength, hardness, toughness, resistance to wear etc.

Manganese:

- It improves ductility, wear resistance and hardenability
- The hardenability is done by quenching which 'Mn' has significant impact
- It diminishes the danger of defect from overheating the process by making it more ~~stable~~ stable

Nickel

1. Its main purpose is to increase ductility and corrosion resistance in combination with other elements namely Chromium.
2. When Chromium contains 18% and Nickel contains 8%, we get an extremely durable stainless steel.

Steel Cen

- i. It improves strength and provide elasticity in spring.
- ii. It also increases the metals' magnetic property.

Titanium

- i. It improves the strength and corrosion resistance.
- ii. It limits austenite grain size.

Vanadium

- i. The formation of vanadium Carbides limits the grain size. This has effect on increasing a material's ductility.
- ii. It also increases the strength, hardness, wear and shock impact resistance. It is beta stabilizer.
- iii. This material has negative impact on material properties.

Molybdenum

- i. Molybdenum has higher impact on steel alloys at high temperature.
- ii. It improves the mechanical properties but also resistance to corrosion and acts as an amplifier for the effect of other alloying elements.

Unit - 3Iron-Carbon system

The relationship between phases in a system as a function of temperature, pressure and composition depicted in the form of maps called equilibrium relationship or equilibrium diagram or phase diagram.

Phase rule

The Gibbs phase rule can be stated as

$$F = C - P + 2$$

where F is the degree of freedom

C is the number of components


P is the number of phases in the system

Phase:- ① Segregation of state of matter like solid, liquid and gas. Liquid has only one phase like gas. But solid, has multiple phases.

Components:- The components refer to the independent chemical species that constitute an alloy

Degrees of freedom:-

The degrees of freedom refer to the number of independent variables associated with the system.

Phases in the Fe-C system

α -Ferrite is an interstitial solid solution of carbon in BCC iron. It exists over the temperature range from -273°C to 912°C .

Austenite (γ) is an interstitial solid solution of carbon in FCC iron. It exists from 912 to 1394°C .

δ -Ferrite (δ_{cc}) is stable from 1394 to 1539°C (the melting point of iron). The maximum solubility of carbon here is 0.09 wt%.

Carbide is an intermetallic compound with formula Fe_3C . The atomic percent of carbon in carbide is 25 and the weight percent is 6.67.

Crystal imperfections

The imperfection in the regular pattern of the crystal is called Crystal imperfection.

The crystal imperfections are following types

- ① Vacancy
- ② Interstitiality
- ③ Interstitial impurity
- ④ Substitutional impurity

Unit cell: A unit cell is an arrangement of atoms and molecules that it has minimum volume and its repeated arrangement in all the three co-ordinate directions form the crystal.

The crystal systems are of

① Cubic system: The three co-ordinate axes of unit cell are of equal axial length. They are inclined to each other at angle of 90° .
 $a = b = c, \alpha = \beta = \gamma = 90^{\circ}$

② Tetragonal system: In this crystal system two axes of unit cell are equal lengths.
 $a = b \neq c, \alpha = \beta = \gamma = 90^{\circ}$

③ Orthorhombic system:

In this crystal system, the axes have different lengths but they are right angle to each other.

$$a \neq b \neq c, \alpha = \beta = \gamma = 90^{\circ}$$

⑤ Rhombohedral system

The axes are not of equal lengths but not necessarily perpendicular to each other.

$$a=b=c, \alpha=\beta=\gamma=90^\circ \text{ and } \angle 120^\circ$$

⑥ Monoclinic system

The three axes can be of any length but one axis is perpendicular to the other two which are inclined among themselves at any angle except 90° .

$$a \neq b \neq c, \alpha = \gamma = 90^\circ, \beta > 90^\circ \text{ or } \beta < 90^\circ$$

⑦ Triclinic system

The three ~~axes~~ are of any length and inclined to each other in any angle, none of which is a right angle.

$$a \neq b \neq c, \alpha \neq \beta \neq \gamma \neq 90^\circ$$

⑧ Hexagonal system

Two axes are equal lengths and third is longer or shorter than other two.

$$a=b \neq c, \alpha=\beta=90^\circ, \gamma=120^\circ$$

Classification of Imperfections

The imperfections are following types

① Point defect:

The defect raised due to the replacement of the atom or an absence from its position is called point defect.

② Line defect:

The line defects are scratches. The atoms or molecules displaced from the regular pattern is called line defect.

2. Surface defect

The irregularities on the material surface due to the irregular position of the particles cause surface defects.

4. Volume defect

The deviation of the regular volume of the matter or object by the deviation or irregular arrangement of the atoms cause volume defects.


Types and Causes of point defects

The point like regions of distortion in the crystal cause point defects.

The point defects are


- i) Vacancy ii) Interstitiality
- iii) Interstitial impurity
- iv) Substitutional impurity.

i. Vacancy: A vacancy is an atomic site from which the atom is missing.




ii. Interstitiality:

An interstitiality refers to an atom displaced from a regular site into an interstitial site.



iii) Interstitial impurity


An interstitial impurity is a small atom occupying an interstitial void space between parent atoms of the crystal.



iv) Interstitial impurity

v) Substitutional impurity

A substitutional impurity is an impurity atom that has substituted for one of the parent atoms on a regular atomic site.



Dislocation

The line imperfections are known as dislocations. The geometry of dislocations can be understood with reference to the two limiting straight line types.

The line defects or dislocations are

- ① The edge dislocation.
- ② The screw dislocation.



Edge dislocation: An edge dislocation extending from the front to the back face of the crystal is formed if distorted the region all along the region of the edge of an incomplete plane in the crystal. The atoms above the edge are compressed whereas those just below are in extension.

The edge dislocation is characterized by Burgers vector.



Screw dislocation

A screw dislocation extending from the right to the left side face of the crystal, it is characterized by a shear strain. The Burgers vector is parallel to the screw dislocation. The positive and negative dislocations are denoted by



Effect of imperfection on material properties

- ① Dislocations are present in crystals due to accidents during the growth of the crystal. The dislocation density is an ordered range from 10^6 to 10^{10} mm^{-3} . Perfect crystals are free from dislocation can be grown.
- ② Dislocation plays an important role in the plastic deformation of metals and alloys. The thin perfect crystals that are totally free from dislocation known as whiskers possess very high strength.
- ③ The presence of dislocation make crystal

The strengthening crystalline materials against this inherent weakness increases the resistance to dislocation motion.

Deformation by slip and twinning




Plastic deformation permanently changes the shape and dimension of a metal. X-ray analysis of a deformed metal shows that during plastic deformation there is no change in the crystal structure. There is no change in the lattice parameters. Only the number of imperfections increase. The microscopic change of shape and dimension can be brought about without any change in the unit cell dimensions. Shows by two processes

① Slip

② Twinning

Slip

In slip atoms move over a number of interatomic distances related to their initial positions. The magnitude of the each step in displacement is one tenth interatomic distance. The orientation of the displaced region is the same as the original deformed region.



Twinning:

In twinning each atom moves by only a fraction of an interatomic distance relative to its neighbours. The orientation of the twinned region is different from the untwinned region. Slip is operative mechanism of plastic deformation at high temperature and lower strain rate, whereas twinning is operative at lower temperatures and higher strain rate.

○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○

Pattern before twinning

○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○

○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○ ○

Pattern after twinning

Effect of deformation on material properties:

- ① The stress required to slip in a perfect ideal crystal can be estimated. If σ is the range of $2\pi/6$ to $4\pi/30$, where G is the shear modulus of crystal. The large difference in the yield stresses arises from the presence of dislocations in the real crystal.
- ② The material free from dislocation (Whisker) possess high strength.
- ③ Slip usually starts from sources within the crystal. A typical source is the Frank-Read source which

Heat treatment

The heat treatment of the materials made of various characteristics of the materials like soft or hard different phases with mechanical properties. The phase transformation is made at temperature. The heat treatment process is applicable both ferrous and non-ferrous alloys.

Process of heat treatment:

Annealing: The heat treatment of iron (steel) at 900°C to 725°C is called annealing with various carbon percentage.

The purpose of annealing is to reduce the hardness, facilitate machining and to relieve tensile stresses. It is a scheduled treatment provided to the metals to lessen them during mechanical working.

i. Full annealing: It consists of heating the steel above the AC_3 temperature in the case of hypoeutectoid steel and the AC_1 temperature in case of hyper-eutectoid steels. The steel is then cooled very slowly (in the furnace) at the rate of a few tenths of degree perhaps. The austenite transforms to coarse pearlite within 50°C of the eutectoid temperature.

ii. Spheroidizing anneal: It is heating to just below AC_1 or thermal cycling in a narrow temperature interval around A_1 . The cementite lamellae in pearlite colonies tend to spheroidize (become small) and thereby reduce their surface area. After prolonged anneal, the spheroidized patches coalesce, becoming fewer in number and more widely spaced.

Recrystallization Anneal

The recrystallization anneal is done at subcritical temperature in the range of $600 - 650^{\circ}\text{C}$. The cold worked晶界 de-crystallizer during this anneal.

Stress-relief anneal:

It is a subcritical treatment given to hypoeutectoid steels up to 0.3% C. The temperature used is up to 600°C . Recovery process occurs without recrystallization. The residual stresses due to cold working or machining are removed by this treatment.

Process anneal:

It is a subcritical treatment given to metals to soften them during mechanical processing. It may or may not involve full crystallization of the cold-work metal.

Normalizing:

Normalizing consists of heating the steel above the Ac_3 temperature for hypoeutectoid compositions and between Ac_1 and Ac_m temperature for hyper-eutectoid compositions. This is followed by cooling in still air. Fine pearlite and proeutectoid ferrite result from this treatment. Normalizing is done for refining the grain structure and for improving the mechanical properties. The hardness and strength obtained after normalizing are higher than those obtained after annealing.

This process is applied to casting and forgings. In casting, normalizing is essential to eliminate the dendritic structure.

Patenting:

This is a special heat treatment process adapted for wire products of medium carbon content. The wire from the austenitizing temperature is passed through a molten lead bath maintained at 500°C .

Quenching and tempering:

Tempering is almost always necessary to remove the residual stresses and to reduce the brittleness of martensite. The actual tempering temperature chosen depends on the final properties desired.

Quenching of a steel is done from the austenitic range to produce martensite. The cooling rate for the steel to get full hardening. Hypoeutectoid steels are heated above the Ac_3 temperature to ensure full austenitization and to avoid the soft ferrite in the final microstructure.

Surface hardening

The surface of the steel is made hard and wear resistance is lost the core remains soft and tough. An improvement of the material is called surface hardening. In steel with more than 0.35% C, the surface can be preferentially hardened by a heat treatment.

1. Induction hardening: An alternating current of high frequency passes through an induction coil enclosing the steel part to be heat treated. The heating time is usually a few seconds immediately after heating, water jets are activated to quench the surface. Martensite is produced at the surface, making it hard and wear resistant. The microstructure of the core remains unaffected. This is suitable for mass production of articles of uniform cross-section.

2. Flame hardening: For large work pieces, such as mill rolls, large gears and complicated cross-sections, induction heating is not easy to apply. In such cases flame hardening is done by means of oxyacetylene torch. Heating should be done rapidly by the torch and the surface quenched before appreciable heat transfer to the core occurs.


3. LASER hardening: A LASER beam can be used for surface hardening. As LASER beam has ^{one} very high intensity, a lens is used to reduce the intensity by producing defocused spot of size ranging from 0.5 to 25 mm. Proper control of energy input is needed to avoid melting. LASER hardening has the advantage of precise control over the area to be hardened, an ability to harden reentrant surface, very high speed of hardening and no separate quenching step. The disadvantage is that the hardening is shallower than in induction and flame hardening.

Carburizing

Carburizing is the most widely used method of surface hardening. Here the surface layer of a low carbon steel ($C \leq 0.25\%$) is enriched with carbon upto 0.8-1.0%. The source of carbon may be a solid medium, a liquid or a gas. In all cases the carbon enters the steel at the surface and diffuses into the steel as a function of time at an elevated temperature. Carburizing is done at $920-950^{\circ}\text{C}$. Carburizing is always done in the austenitic state.

2. Pack Carburizing

The articles to be carburized are packed in a box embedding them in a powdery mixture of 85% charcoal and 15% of energizers such as BaCO_3 .




Typical carburizing times are 6-8 hours.

ii. Selective Carburization:

The copper is electroplated to a thickness of 0.05 mm in regions where carburization is not desired or a refractory paste of fireclay mixed with asbestos coke applied. Control of temperature and penetration depth is less in pack carburizing as compared to liquid and gas carburizing.


iii. Gas Carburizing:-

The gas carburizing proceeds with a mixture consisting of 5-15% methane (or propane) in a neutral carrier gas & used. The methane decomposes according to the following reaction





iv. Liquid Carburizing

It is an outgrowth of cyaniding process discussed below. A typical bath composition is 8% NaCN , 82% BaCl_2 and 10% NaCl . The following reactions take place




Cyaniding

Cyaniding is done in a liquid bath of NaCN with the concentration varying between 30 and 97%. Both carbon and nitrogen enter the steel



Nitriding

In contrast to the processes described, nitriding is carried out in the ferrite region. No phase changes occurs in nitriding. The part to be nitrided should possess the required core properties prior to nitriding.



The solubility of nitrogen in ferrite is small. Most of the nitrogen that enters the steel forms hard nitrides (Fe_3N). A typical nitriding steel contains alloying elements of 1.7-Al, 1.5-Y-O₂ and 0.8-Y-Mo. The temperature of nitriding is 500 - 690°C. The time for a case depth of 0.02mm is about 2 hrs. An extremely hard case is produced with hardness in the range of 1000 - 2000 VHN.

Non-ferritic alloy

Aluminum alloys:-

The aluminum alloys are considered one among the light alloys. They have some special characteristics like high Corrosion resistance, high electrical conductivity, high thermal conductivity. But they have large requirement for energy for production.

Composition of aluminum alloys:-

The alloys consist of Copper, Manganese, Silicon, magnesium, Zinc along with aluminum.

Properties of aluminum alloys

- (1) Light weight
- (2) High Corrosion resistance
- (3) High electrical conductivity
- (4) High Thermal Conductivity
- (5) Impenetrability to oxygen, moisture and micro-organisms

Uses

- (1) Pure aluminum is used in electrical industries, packaging industry and for chemical process equipment and for architectural purpose.
- (2) Al-Mn and Al-Mn-Mg alloys are used for beverage cans, cooking utensils, buildings and roofing sheets.
- (3) Al-Si alloys are used at welding and brazing electrodes.
- (4) Al-Ce alloy, Ce-Al₂ and associated plates are used to fabricate sheets, plates and extrusion for structural purpose and forgings for air craft structures.

Copper Alloys

Among the common metals Copper is the best conductor of heat and electricity, next only to the noble metals silver and gold. The common impurity in copper, oxygen, is very easily removable.

I. Cu-Al → aluminum bronze

Cu-Sn → phosphor bronze

Cu-Si → silicon bronze

In Cu-Sn solubility of Tin (Sn) in copper is about 17% at 520°C and decreases continuously cooling to the room temperature.

In Cu-Si solubility of Si is 5.3% at 852°C and decreases with decreasing temp.

The solubility of aluminum is 9.5% in aluminum bronze at 500°C.

II. Brass

The brasses are alloys of copper and zinc. The Cu-Zn phase diagram indicates no formation of α & β phase with heat treatment.

The solution of 20% Zn form reddish in color and above 20% the colored will be yellow.

70/30 brass → cartridge brass

Cu Zn

70/29/1% brass → Admiralty brass

Cu Zn

60% / 40% → Muntz metal

Cu Zn

60% / 39% / 1% → Naval brass

Cu Zn

Babbit

The white metals consist of a base matrix in which either lead based or tin based. A typical lead based consists of 10% Pb, 10% Sb, 10% Sn.

The tin based babbitt is 90% Sn, 5% Sb and 5% Cu.

Bearing materials:-

The properties required for bearings are

- ① The friction between the bearing and rotating part should be as small as possible.
- ② The wear at the contacting surfaces should be as low as possible.
- ③ The bearing must capable of withstanding pressure due to axial from misalignment.
- ④ It must contain a relatively low melting component which will soften or melt and prevent seizure.

There are different types of bearing materials

- ① Lead based :- 80% Pb, 10% Sb and 10% Sn
- ② Tin based :- 90% Sn, 5% Sb and 5% Cu

Spring materials


The spring steel have carbon contents in the range of 0.5 - 0.65%. They are quenched and tempered to high level of yield strength. A spring must possess a high resilience. It must capable of storing a large amount of elastic energy. so that it can spring back without permanently deforming. The quantity of % should be maximized for this purpose. The Young's modulus y being a structural intensive property, a large increase in the yield strength is the key to achieve a high resilience. The tempering is done to give a yield strength of about 150 MPa.

The alloying elements in a spring steel have several functions. They increase the hardenability to be severe functioning. They increase the hardenability to be hardenability is obtained without resorting to deep quenching. The presence of silicon in the 50Si2Mn90 spring steel serves the additional purpose of reducing softening during tempering. So the residual stresses are relieved without much loss in hardness and strength. Vanadium in the 50Cr1V23 steel prevents grain coarsening austempering and improves the toughness of the steel.

Polymers

The polymers are the compounds prepared by the various organic and inorganic methods.

The polythene is a polymer prepared by the polymerisation of ethene.



The other polymers are teflon, PVA, PLLA, PGA, PEG, PEU etc.

Properties of polymers

- ① The polymers are light weight.
- ② The thermoplastic polymers are used as the insulator for insulation.
- ③ The thermosetting pastes are used for the fabrication of different objects for moulding process.

The polymers have versatile uses.

- ④ The polymers like parax and styrene are used as lacquers.
- ⑤ The electrical equipment and wires are coated with polymers for insulation.
- ⑥ The body of the car, buses are made from the polymers for their anti-corrosion properties.
- ⑦ The polymers are also used as biomaterial for medical applications.
- ⑧ The elastomers like natural or synthetic rubbers are used to make tyres of the vehicles and clothes.

Elastomers

The polymers which shows high elasticity called elastomers. The synthesis of natural rubbers are good elastomers.

The elastomers are prepared by the polymerisation of the natural gum at the rubber plant or prepared in the laboratory by various synthetic materials. The elastomers were used as containers, multipurpose uses. They used as containers, compressible objects like tyres and dolls along with game equipment like tennis ball, football and fabrics.

Composites Composite and Ceramic

13

The Composites are the composites which are formed by compaction or reinforcement of different materials with each other according to the required characteristic.

If the particle size of the constituent elements in the composites are in micrometer, they are called microcomposite and if in nanometer, they are called nano composite.

According to the constituent elements the composites are (i) metal based (ii) ceramic based, and (iii) polymer based.

The composites have various uses like medical application of different circuit elements, aircraft body and many more.

Ceramics

The ceramics are non metallic or metal oxides based compounds. The ceramics have high brittle and stiff property but they have low mechanical properties due to the high corrosion quality the ceramics are used for various purpose like architecture and medical application and many more. The ceramics are biocompatible materials. So they are widely used as biomaterials. CaP (Ceramic phosphate), HA (hydroxyapatite), clay are basically ceramics. The bioglass(B) are currently used as biomaterials.

Biophysics


Biophysics is an interdisciplinary science that applies approaches and methods traditionally used in physics to study biological phenomena. Biophysicists cover all the levels of biological organization from molecules to organismic and population. Biophysical research shows significant overlap with biochemistry, molecular biology, physical chemistry, physiology, nanobiotechnology, biengineering, computational biology, biomechanics, developmental biology and systems biology.

Biological organization

Biological organization is a hierarchy of complex biological structure and systems that defines life using a reductionist approach. The hierarchy extends from atoms to biosphere. The higher level scheme is referred to as an ecological organization or as the first hierarchical ecology.


BO of life is a fundamental premise of numerous areas of scientific research, particularly in the medical sciences.

BO Levels



Biochemistry: Biologic chemistry is the study of chemical processes within and relating to the living organisms. Sub discipline both biology and chemistry.

Biochemistry



Molecular Biology

Molecular biology is the branch of biology that seeks to understand the molecular basis of biological activity in or between cells including biomolecular synthesis.

Physical Chemistry

Physical chemistry is the study of macroscopic and microscopic phenomena in chemical system in terms of the principle, practice and concept of physics such as motion, energy, force, time, thermodynamics, quantum chemistry, statistical mechanics, analytical dynamics and chemical equilibrium.

Important relationships

- ① Intermolecular forces that act upon the physical properties of materials (plasticity, tensile strength, surface tension in liquids)
- ② Reaction kinetics on the rate of ~~surface reaction~~